Riverbend Soil Consulting, Inc.

P.O. Box 2879 Rome, GA 30164-2879 Phone (706) 234-9444 FAX (706) 291-2914

Soil Analysis Report

		Son Ana	nysis ixcho	IL.			
Client: Steve	Steve Slocumb			Phone #:			
Client Address:	nt Address:				Cell/Pager #:		
Site Location: 5.64 A	5.64 Acre Tract Whitecliff Drive				County: Gilmer		
Level of Study: 3		(1-Reconnaissance, 2-P	reliminary, 3-High Inten	sity, 3ss-Special Study)	Job Number:	7553	
	SEI	RIES DE	SCRIP	ΓIONS			
Dat	e Evaluated:		ptember 18, 20				
Test Hole Number	#1	#2	#3	#4	#5	#6	
Series Name	Cowee	Hayesville	Evard	Evard			
Slope (Percent)	17%	21%	22%	21%			
Bedrock Depth (inches)	soft at 30" hard >48"	>60"	>60"	>60"			
Seasonal High Water Table	>60"	>60"	>60"	>60"			
Suitability Code	A	A	A	A			
Estimated Percolation Rate	45	45	45	45	I.S.		
Optimum Percolation Depth	24"	24-36"	24-36"	24-36"	e	×	
Hydraulic Loading Rate							
Additional Commer	nts:	*					
W.					MICAN	KIRK TA	
					(Ben I	7 38	
					18 9	A	

Soil Classifier:

Additional Comments and Notes

Code A: (should work)	
SUITABILITY CODE: Soil series should have ability to function as suitable absorption	1
field with proper design, installation, and maintenance.	1278/AM/States and AM
	Harrist enink av an an armon announce
	······································
	international and the second section of the se
	MidwhAlddhpurvernerezhbidezhenne

	hr/denburú-elidina-violainideau-dudelinidael
	timisarisasan namananamamaisatid

	profiles have greater the profile profiles and the profil

•	

^{*}Cut and/or fill of acceptable soils voids this report.

^{*}Boundaries and borings are located from ground measurements taken from readings by a Trimble PRO XRS GPS and slope readings are from a Suunto Clinometer. Holes are marked by survey ribbon or wire flags.

^{*}Please note that all findings reported are based on professional opinion and do not imply approval or disapproval for permitting. Decisions and permitting is the responsibility of the local environmental health department.

^{*}Due to the variances in natural soil conditions and effects of uncontrolled construction practices, a positive report does not guarantee the future performance of septic system.

